



**BLUE ROCK
ENVIRONMENTAL, INC.**

Mr. Robert Stone
HCDEH
100 H Street, Suite 100
Eureka, California 95501

March 20, 2006

Re: Well Destruction Report
Indianola Market
7769 Myrtle Avenue
Eureka, CA
Project No. NC-18
LOP # 12690

Dear Mr. Stone,

This report presents the results well destruction activities at 7769 Myrtle Ave., Humboldt County, California (site) (Figure 1), and was prepared for Mrs. Beverly Alto and Mr. Jerry Avila by Blue Rock Environmental, Inc. (Blue Rock).

In order to restore the site to pre-investigation conditions, the existing monitoring wells were destroyed.

Well Destruction Activities

Blue Rock obtained well destruction permits from the HCDEH prior to initiating field activities.

On March 16, 2006, the sites monitoring wells (MW-1, to MW-5) were destroyed by overdrilling and grout methods. A Blue Rock scientist supervised Mitchell Drilling Environmental, a C-57 licensed driller based in Eureka, California, perform well destruction activities.

Prior to destruction, each well was measured to verify the depth to bottom of the casing. Each well was then destroyed by overdrilling the well annulus and grouting the boring to finished grade. The wells were overdrilled with the same size augers used to install the wells, and all the well materials were removed. Well destruction information is included in Table 1, and locations of destroyed wells are shown on Figure 1.


Soil cuttings generated from well destruction activities were placed in (1) 55-gallon DOT rated steel drum, stored on site and await future transportation and disposal at an appropriate facility.

This letter reports on the final activities related to this project. The case has received regulatory closure, and no further work is planned or warranted.

If you have any questions regarding this project, please contact us at (707) 441-1934.

Sincerely,
Blue Rock Environmental, Inc.

Prepared by:

A handwritten signature in black ink, appearing to read "Andrew LoCicero", followed by a horizontal line.

Andrew LoCicero
Project Manager

Attachments:


- Site Plan (Figure 1)
- Well Construction and Destruction Details (Table 1)

Distribution:

- Beverly Alto, 7803 Myrtle Avenue, Eureka, CA 95503
- Jerry Avila, 7555 Myrtle Avenue, Eureka, CA 95503
- Kasey Ashley, NCRWQCB

EXPLANATION

- B-1 Boring location 10/01 & 6/03
- MW-1 Monitoring well (destroyed)
- ⊙ 2 September 1998 sample location
- Approximate property line
- - - Limits of excavation
- ▨ Former underground storage tank (UST) location
- Former dispenser location



SITE PLAN

Indianola Market
7769 Myrtle Ave.
Eureka, California



BLUE ROCK
ENVIRONMENTAL, INC.

Project No.
NC-18

Report Date
3/06

Figure
1

Table 1
Well Construction and Destruction Details
Indianola Market
7769 Myrtle Avenue
Eureka, CA
Project # NC-18

Well Identification	Date Installed	Installed by	Casing Diameter (inches)	Total Depth (feet)	Blank Interval (feet)	Screened Interval (feet)	Slot Size (inches)	Filter Pack (feet)	Bentonite Seal (feet)	Cement (feet)
MW-1**	10/10/01	Clearwater	2	20	0-3	3-20	0.02	2-20	1-2	0-1
MW-2**	10/10/01	Clearwater	2	20	0-3	3-20	0.02	2-20	1-2	0-1
MW-3**	10/10/01	Clearwater	2	20	0-3	3-20	0.02	2-20	1-2	0-1
MW-4**	10/7/02	Clearwater	2	20	0-3	3-20	0.02	2-20	1-2	0-1
MW-5**	10/7/02	Clearwater	2	20	0-3	5-20	0.02	2-20	1-2	0-1

** Monitoring well destroyed by overdrilling and grouting on March 16, 2006.